



# Wyndmaster 100TR

## Take-Up System



## FEATURES

- Simple Operator Controls
- Variable Speed DC Spindle Drive
- Uhing Traverse Feeder
- Dancer Loop Control
- Adjustable Tension
- Selectable Overwind / Underwind Operation

## OPTIONS

- Non-Contact Loop Control
- Spindle Adapters to Accept Various Reel Cores
- Collapsible Mandrel
- High or Low Limit Shutdown Contacts



*Customized Products  
For Any Applications!*

[jcrautomation.com](http://jcrautomation.com)

JCR Automation  
1426 Ryan Rd  
New Haven, IN 46774  
Phone: 260-493-6606





# Wyndmaster 100TR

## Specifications

### POWER REQUIREMENTS

120 VAC, single phase, 5A

### MATERIAL WIDTH (MAX)

3.0 Inches

### REEL DIAMETER (MAX)

24.0 Inches

### SPINDLE MOTOR

76 RPM, 1/8 HP, DC

### FEED RATE CAPACITY

1200 IPM @ 5" Core

### SPINDLE DIAMETER

(Per Customer Request)

### DRIVE PIN




(Per Customer Request)

### TRAVERSE PITCH

0.00 - 2.00 Inches

### FEED DIRECTION

Left to Right or Right to Left (Per Customer Request)



Customized Products  
For Any Applications!

[jcrautomation.com](http://jcrautomation.com)

JCR Automation  
1426 Ryan Rd  
New Haven, IN 46774  
Phone: 260-493-6606

